


SCANDIC


Art. 26370018/14



Achtung! Fachgerechte Montage vom Fachmonteur gewünscht !
Attention! Preferably professional assembling assistant!
Uzmanību! Montāžu vēlams veikt profesionālam montierim!

Teil Nr. Pièces Nr. Pieces No. Часть Ном. Kawalek Nr. Parça No Kusù Nr. Kusov Nr. Pezzi Nr. Nr piese. Darab száma. Stukken Nr. Kārtas nr.	Anzahl Quantité Quantity Количество Ilość Miktar Množství Množstvo Quantità Cantitatea Mennyiség Hoeveelheid Skaitis	Kasten Nr. Colli Nr. Colli No. Коробка Ном. Polu Nr. Kutusu Nr. Kolonka Č. Počet balení Colli Nr. Nu pachete Colli száma. Colli Nr. Kastes nr.	Maß, mm Dimensions, mm Dimensions, mm Размеры, mm Wymiary, mm Boyutlar, mm Rozměry, mm Rozmery, mm Dimensioni, mm Dimensiuni, mm Méterek, mm Afmetingen, mm Izmēri, mm	
06	1	3/5	1894 x 548 x 38	
07	1	3/5	1894 x 548 x 38	
08	1	4/5	1501 x 864 x 3	
102	2	4/5	150 x 42 x 34	
103	2	4/5	150 x 42 x 34	
104	1	1/5	132 x 80 x 22	
040	1	2/5	1350 x 550 x 18	
044	1	4/5	1894 x 524 x 18	
045	1	2/5	1310 x 510 x 18	
046	5	1/5	432 x 484 x 16	
047	1	1/5	856 x 502 x 16	
048	1	1/5	856 x 524 x 18	
049	1	2/5	1270 x 45 x 22	
051	1	4/5	1902 x 440 x 3	
053	1	5/5	1468 x 420 x 18	
054	1	5/5	1468 x 420 x 18	
055	1	5/5	1866 x 420 x 18	
056	1	1/5	856 x 100 x 16	
057	1	1/5	432 x 100 x 16	
058	1	1/5	856 x 384 x 16	
059	2	2/5	196 x 843 x 18	
060	2	2/5	475 x 145 x 16	
061	2	2/5	475 x 145 x 16	
062	2	2/5	796 x 145 x 16	
063	2	2/5	459 x 145 x 16	
064	4	2/5	468 x 399 x 3	
065	2	4/5	1266 x 45 x 18	
066	2	4/5	482 x 45 x 18	
067	2	1/5	278 x 60 x 18	

idp68443/1



idp68443/1



H1
(x61)



H15
(x4)



D307
(x8)



A25
(x16)



A89
(x12)




D19
(x28)



D196
(x8)



D198
(x8)




D2
(x42)




D3
(x18)



D21
(x2)




D45
(x32)



A27
(x1)




D5
(x24)



A59
(x10)




A1
(x38)



A5
(x1)



D4
(x31)




E87
(x2)

485mm



D63
(x20)




D138
(x12)

LV Godātais pircēj, šeit Jums ir iespēja izmērīt pievienotās skrūves.


UK Dear customer, here you have the possibility of measuring the supplied screws.

D Sehr geehrter Kunde, hier haben Sie die Möglichkeit mitgelieferte Schrauben nachzumessen.






G88
(x6)



G87
(x3)




G75
(x9)




H20
(x2)




A133
(x2)




D31
(x2)



L2
(x2)



L3
(x1)
850mm



B102
(x5)


L=408mm
(352mm)




A29
(x10)

idp68443/1

1



2








3


H1
(x24)

D19
(x4)

D196
(x8)




idp68443/1







idp68443/1

5


D197
(x4)


A5
(x1)









6

A5
(x1)





D45
(x4)

H1
(x1)






A27
(x1)



7



8



9

A1
(x2)


D3
(x12)

D19
(x12)

H1
(x8)

G75
(x6)

L2
(x1)



10

A1
(x2)







D19
(x8)

H1
(x4)

G75
(x3)





D21
(x2)

L2
(x1)



11






D4
(x3)



idp68443/1

12

$\frac{D4}{(x3)}$ $\frac{D3}{(x6)}$





idp68443/1

13

H15
(x4)

A59
(x4)






idp68443/1


14

A25
(×16)

E87
(×2)









2x







idp68443/1

15



idp68443/1

16



idp68443/1


17

A89
(x6)


A1
(x6)

D138
(x6)



1.



2.



3.




A89
Ø6,2x12



A25
Ø6,2x10,5

idp68443/1

18






D138
(x6)




A1
(x6)



A89
(x6)




1.



D138


2.



D138

A89

3.



D138

A1



A89
Ø6,2x12



A25
Ø6,2x10,5


19

A1
(x4)



D45
(x14)

A59
(x6)


D2
(x9)





D31
(x2)






6x



9x







14x



2x

idp68443/1



20



23-33

idp68443/1




21



idp68443/1

22


D4
(x9)




idp68443/1

23








H20
(x2)

A133
(x2)





D31
(x2)




idp68443/1


24


D63
(x20)




25


L3
(x1)




26






A1
(x18)




G87
(x3)



G88
(x6)




$X > Y$




idp68443/1







27



B102
(x3)



A29
(x6)





idp68443/1

28



$\frac{D2}{(\times 12)}$

$\frac{H1}{(\times 24)}$

$\frac{D5}{(\times 16)}$



2x







29

$\frac{D5}{(\times 8)}$









$\frac{D4}{(\times 4)}$

2x



idp68443/1

32



32-33

idp68443/1

