













70962

A30	 ø8x40	x60	B1		x1
A34		x14	B21		x6
A52	 ø10x13	x8	B102		x2
A53	 ø10x18	x8	C12		x18
A54	 ø14x13	x2	C31	 ø3,5x30	x28
A55		x7	C75	 ø4x50	x4
A56	 ø7x60	x8			

Dear customer.


Here you have the possibility of measuring the supplied screws.


Geehrter Kunde.

Hier haben Sie die Möglichkeit die mitgelieferten Schrauben nachzumessen.



Cher client,

Ici vous avez la possibilité de mesurer les vis livrées.











Teil Nr. Pièces nr. Pieces nr.	Anzahl Quantité Quantity	Maß,mm Dimensions,mm Dimensions,mm	✓
1	2	1143 x 180 x 25	
2	2	1143 x 180 x 25	
3	4	900 x 152 x 25	
4	4	900 x 150 x 19	
5	1	1850 x 152 x 55	
6	1	1850 x 152 x 55	
7	1	1270 x 152 x 25	
8	1	1630 x 152 x 25	
9	1	1118 x 209 x 25	
10	1	1118 x 209 x 25	
11	3	310 x 92 x 25	
12	14	897 x 69 x 18	
13	1	69 x 18 x 18	


A30		$\varnothing 8 \times 40$	x32
A52		$\varnothing 10 \times 13$	x8
A53		$\varnothing 10 \times 18$	x8
B1			x1
C12			x16

1




70962




A30		$\varnothing 8 \times 40$	x12
-----	---	---------------------------	-----

A56		$\varnothing 7 \times 60$	x6
-----	--	---------------------------	----




2



B1		x1
----	--	----

B21		x6
-----	--	----






70962




A30	 $\varnothing 8 \times 40$	x6
A34		x6
A54	 $\varnothing 14 \times 13$	x1
A55		x3


B1		x1
C12		x1

3







70962


A30	 $\varnothing 8 \times 40$	x2
A54	 $\varnothing 14 \times 13$	x1
A56	 $\varnothing 7 \times 60$	x2
B1		x1


B102		x2
C12		x1


4





70962


A30		ø8x40	x8
-----	---	-------	----

A34			x8
-----	--	--	----



A55			x4
-----	--	--	----

5




C75		ø4x50	x4
-----	---	-------	----

6



70962



C31



ø3,5x30

x28

7



70962